REVISED EVALUATION REPORT (As Per Rule 35 of PP Rules, 2004)

Name of Procuring Agency
 Method of Procurement
 National Transmission and Despatch Co. Ltd (NTDCL)
 International Competitive Bidding (ICB)

Design, Manufacturing & Supply of complete

Hardware String including Pre-RTV Coated Disc Insulators (Porcelain or Toughened Glass) for 500kV Lines for Evacuation of Power from K-2/K-3 Nuclear

Power Plants.

4. Tender Inquiry No.

NPP-04M(R)-2020

PPRA Ref No.

3.

TS414869E

6. Date & Time of Bid Closing

Title of Procurement

14/05/2020 at 11:00 A.M.

7. Date & Time of Bid Opening

Technical: 14/05/2020 at 11:30 A.M. Financial: 24/12/2020 at 11:30 A.M.

8. No. of Bids Received

80

9. Criteria for Bid Evaluation

<u>Evaluation and Comparison of Bid as per Section-I</u> "Instructions to Bidders" of Bidding Documents

10. Details of Bid(s) Evaluation

Name of the Bidders	Marks Technical (If Financial (If Applicable)		Quoted Bid Price (CIF Karachi)	Corrected/ Evaluated/Disc ounted Bid Price (CIF Karachi)	Total Corrected & Discounted Bid Price (PKR)	Remarks	
M/s. Sediver SAS, France	NIL	NIL	Euro Euro 2,319,368,409 Respons				
M/s. Sichuan YiBin Global Group Co. Ltd. (SYGG), China	NIL	NIL	Non-Responsive Reasons of non-responsiveness are as under: Grievance Redressal Committee NTDC has declared the bidder as Non-responsive because the authenticity of the end user certificates (including shattering performance certificate) provided with the proposal could not be ascertained, hence the bidder could not substantiate his experience and capability as per clause IB-3A Section-II: BDS & clause 3.12 Section-VII: Technical Provision of the bidding document. In view of the above, the bid is determined to be non-responsive pursuant to clause IB 30 of section-II of the Bidding Documents.				

Revised du . Rel 134. Polt

Page 1 of 3

M/s. Suzhou			Non-Responsive		
Porcelain			Reasons of non-responsiveness are as under:		
Insulator Works Co. Ltd. (SPIW),	NIL	NIL	Bidder's experience & capability as per clause IB-3.1A a 2(ii), Section-II: BDS, could not be established. Also Bidder showed its inability to perform the string design & E-field modelling.		
China			In view of the above, the bid is determined to be non-responsive pursuant to clause IB 30 of section-II of the Bidding Documents.		
			Non-Responsive		
			Reasons of non-responsiveness are as under:		
M/s. Dalian Insulator Group T&D Co. Ltd.,	NIL	NIL	1. Documents submitted by bidder as per clause IB-3.1A (a) 1 in Section-II: BDS, were ambiguous and incomplete, therefore not acceptable pursuant to Section-II: BDS clause IB-3A.		
China			2. Bidder's experience & capability as per clause IB-3.1A a 2(ii), Section-II: BDS, could not be established.		
			In view of the above, the bid is determined to be non-responsive pursuant to clause IB 30 of section-II of the Bidding Documents.		
			Non-Responsive		
			Reasons of non-responsiveness are as under:		
M/s. Zhejiang	NIL	NIL	1. Bidder does not meet the Financial criteria laid out in clause IB-3.1A a 6, Section-II: BDS.		
JinLihua Electric Co. Ltd., China			2. Manufacturing experience requirement laid in IB-3A-(2)-(ii) Section-II: BDS of bidding documents could not be established.		
Eta., Cimia			3. Bidder could not establish/prove the eligibility as per bidding document clause IB 3A (3) Section-II and clause 3.12 of Technical Provisions, respectively.		
			In view of the above, the bid is determined to be non-responsive pursuant to clause IB 30 of section-II of the Bidding Documents.		
			Non-Responsive		
M/s.			Reasons of non-responsiveness are as under:		
Shandong Ruitai Glass	NIL	NIL	1. Bidder could not establish/prove the eligibility as per bidding document clause 3.12 of Technical Provisions.		
Insulator Co. Ltd., China			2. Hardware manufacturer of the bidder was disqualified.		
			3. Bidder's experience & capability as per clause IB-3.1A a 2(ii), Section-II: BDS, could not be established.		

			In view of the above, the bid is determined to be non-responsive pursuant to clause IB 30 of section-II of the Bidding Documents.
			Non-Responsive
M/s. Nanjing Electric Group Co. Ltd., China	NIL	NIL	Reasons of non-responsiveness are as under: 1. From the submitted documents, manufacturing experience requirement laid in IB-3A-(2)-(ii) Section-II: BDS of bidding documents could not be established/substantiated. 2. Bidder's experience & capability as per clause IB-3.1A a 2(ii), Section-II: BDS, could not be established.
			3. Bidder could not establish/prove the eligibility as per bidding document clause 3.12 of Technical Provisions. In view of the above, the bid is determined to be non-responsive pursuant to clause IB 30 of section-II of the Bidding Documents.
			Non-Responsive
M/s. Yuzhnouralsk Insulators & Fitting Plant (YuAIZ AO), Russia	NIL	NIL	Reasons of non-responsiveness are as under: 1. Bidder could not establish/prove the eligibility as per bidding document clause IB 3A (3) Section-II and clause 3.12 of Technical Provisions, respectively. 2. Bidder's experience & capability as per clause IB-3.1A a 2(ii) Section-II: BDS, could not be established. In view of the above, the bid is determined to be non-responsive pursuant to clause IB 30 of section-II of the Bidding Documents.

11. Lowest Evaluated Responsive Bidder

M/s. Sediver SAS, France

12. Any other additional/supporting information, the procuring agency may like to share

Nil

Signature		
Signature	Cianatura	
	Signature	

Official Stamp CHIEF ENGINEER (MP&M) NTDC

Note: The above evaluation results are based on detailed Bid Evaluation Report (BER) and correct to best of our knowledge, however, in case of any discrepancy, the content of original BER shall prevail.

EVALUATION REPORT (As Per Rule 35 of PP Rules, 2004)

1. Name of Procuring Agency

2. Method of Procurement

3. Title of Procurement

National Transmission and Despatch Co. Ltd (NTDCL)

International Competitive Bidding (ICB)

Design, Manufacturing & Supply of complete Hardware String including Pre-RTV Coated Disc Insulators (Porcelain or Toughened Glass) for 500kV Lines for Evacuation of Power from K-2/K-3 Nuclear

Power Plants.

4. Tender Inquiry No.

NPP-04M(R)-2020

5. PPRA Ref No.

TS414869E

6. Date & Time of Bid Closing

14/05/2020 at 11:00 A.M.

7. Date & Time of Bid Opening

Technical: 14/05/2020 at 11:30 A.M.

Financial: 24/12/2020 at 11:30 A.M.

8. No. of Bids Received

80

9. Criteria for Bid Evaluation

<u>Evaluation and Comparison of Bid as per Section-I</u>
"Instructions to Bidders" of Bidding Documents

10. Details of Bid(s) Evaluation

Name of the Bidders		rks Financial (If Applicable)	Quoted Bid Price (CIF Karachi)	Corrected/ Evaluated/Dis counted Bid Price (CIF Karachi)	Total Corrected & Discounted Bid Price (PKR)	Remarks	
M/s. Sichuan YiBin Global Group Co. Ltd. (SYGG), China	NIL	NIL	CNY 78,238,984.06	CNY 78,238,984.06	1,789,325,565	Responsive	
M/s. Sediver SAS, France	NIL	NIL	Euro 12,913,819.80	Euro 13,261,869.80	2,319,368,409	Responsive but higher in Price	
M/s. Suzhou Porcelain Insulator Works Co.	NIL	NIL	Non-Responsive Reasons of non-responsiveness are as under: Bidder's experience & capability as per clause IB-3.1A a 2(ii), Section-II: BDS, could not be established. Also Bidder showed its inability to perform the string design & E-field modelling.				

Page 1 of 3

32 stile 134.

0 33801

Ltd. (SPIW), China			In view of the above, the bid is determined to be non-responsive pursuant to clause IB 30 of section-II of the Bidding Documents.			
			Non-Responsive			
			Reasons of non-responsiveness are as under:			
M/s. Dalian Insulator Group T&D	NIL	NIL	1. Documents submitted by bidder as per clause IB-3.1A (a) 1 in Section-II: BDS, were ambiguous and incomplete, therefore not acceptable pursuant to Section-II: BDS clause IB-3A.			
Co. Ltd., China	7412	NIL	2. Bidder's experience & capability as per clause IB-3.1A a 2(ii), Section-II: BDS, could not be established.			
			In view of the above, the bid is determined to be non-responsive pursuant to clause IB 30 of section-II of the Bidding Documents.			
			Non-Responsive			
	NIL	NIL —	Reasons of non-responsiveness are as under:			
M/s. Zhejiang JinLihua Electric Co. Ltd., China			1. Bidder does not meet the Financial criteria laid out in clause IB-3.1A a 6, Section-II: BDS.			
			2. Manufacturing experience requirement laid in IB-3A-(2)-(ii) Section-ii: BDS of bidding documents could not be established.			
			3. Bidder could not establish/prove the eligibility as per bidding document clause IB 3A (3) Section-II and clause 3.12 of Technical Provisions, respectively.			
			In view of the above, the bid is determined to be non-responsive pursuant to clause IB 30 of section-II of the Bidding Documents.			
			Non-Responsive			
			Reasons of non-responsiveness are as under:			
M/s. Shandong Ruitai Glass Insulator Co. Ltd., China	NIL	NIL	1. Bidder could not establish/prove the eligibility as per bidding document clause 3.12 of Technical Provisions.			
			2. Hardware manufacturer of the bidder was disqualified.			
			3. Bidder's experience & capability as per clause IB-3.1A a 2(ii), Section-II: BDS, could not be established.			
			In view of the above, the bid is determined to be non-responsive pursuant to clause IB 30 of section-II of the Bidding Documents.			

			Non-Responsive		
	NIL	NIL	Reasons of non-responsiveness are as under:		
M/s. Nanjing Electric			1. From the submitted documents, manufacturing experience requirement laid in IB-3A-(2)-(ii) Section-II: BDS of bidding documents could not be established/substantiated.		
Group Co. Ltd., China			2. Bidder's experience & capability as per clause IB-3.1A a 2(ii), Section-II: BDS, could not be established.		
			3. Bidder could not establish/prove the eligibility as per bidding document clause 3.12 of Technical Provisions.		
			In view of the above, the bid is determined to be non-responsive		
			pursuant to clause IB 30 of section-II of the Bidding Documents.		
	NIL	NIL	Non-Responsive		
M/s.			Reasons of non-responsiveness are as under:		
Yuzhnouralsk Insulators & Fitting Plant (YuAIZ AO), Russia			1. Bidder could not establish/prove the eligibility as per bidding document clause IB 3A (3) Section-II and clause 3.12 of Technical Provisions, respectively.		
			2. Bidder's experience & capability as per clause IB-3.1A a 2(ii), Section-II: BDS, could not be established.		
			In view of the above, the bid is determined to be non-responsive pursuant to clause IB 30 of section-II of the Bidding Documents.		

11. Lowest Evaluated Responsive Bidder

M/s. Sichuan YiBin Global Group Co. Ltd. (SYGG), China

12. Any other additional/supporting information, the procuring agency may like to share

Nil

Signature			
- B. I. S. C.			

Official Stamp CHIEF ENGINEER (MP&M) NTDC

Note: The above evaluation results are based on detailed Bid Evaluation Report (BER) and correct to best of our knowledge, however, in case of any discrepancy, the content of original BER shall prevail.